



TOOLS



CATALOG ~42

Langdon Acme Mitre Boxes



Ball Bearing Saw Guides. Ball Bearing Swinging Lever

The Langdon Acme box has been the outstanding mitre box for many years. Now to its many other fine features have been added: ball bearing saw guides, which practically eliminate the friction between the guides and saw back, and a full ball bearing lever, making it extremely easy to swing the saw from one angle to another. Greatly improved angle and length attachments (not illustrated) have also been added.

The thumb lever at the front locks or releases the saw supports so that they may be swung to any angle. A notched bed plate provides a positive lock at the most used angles. Lever can also be set at any intermediate angle. Easily read graduated arc and index plate shows points at which to set saw for certain cuts. Extension lever for quick acting adjustment on all sizes. Two spring locks in the guide posts hold the saw elevated when not in use.

Red enameled steel bottom plates roughened to prevent the work from slipping. Main castings nicely black enameled. Bright parts nickel plated.

Each box equipped with the highest grade 11 point back saw, tested out in the box with which it is shipped. While boxes without saws can be supplied, accuracy is guaranteed only when saws are fitted at the factory.

Capacity—All sizes—10½ inches at right angles, 7 inches at mitre.
Length of bed, 19¾ inches; width, 4½ inches.

Prices Complete with Saw


	Size Saw	Net Weight	Packed	Code	Price Each
No. 71A	22 x 4 inches	24 lbs.	37 lbs.	LACER	\$28.20
No. 72A	24 x 4 inches	25 lbs.	38 lbs.	LADDE	28.50
No. 73A	26 x 4 inches	25 lbs.	38 lbs.	LADIM	29.00
No. 74A	28 x 5 inches	26 lbs.	40 lbs.	LADLE	32.00
No. 75A	30 x 5 inches	26 lbs.	41 lbs.	LAGER	34.25

Prices without Saw

No. 1071A	For 4-inch Saw	21 lbs.	30 lbs.	LAIRD	\$21.00
No. 1074A	For 5-inch Saw	23 lbs.	32 lbs.	LAITY	22.55

Packed one in a wooden box.

Parts for Langdon Acme Mitre Boxes



Nos. 68-75 and 71A-75A



Parts for Langdon Acme Mitre Boxes

Nos. 68-75 and 71A-75A

		For Boxes Nos.		Each
AA	Binder	71-75	71A-75A	\$0.15
AB	Index Plate	68-75	71A-75A	.25
AD	Gib	68-75	71A-75A	.50
AE	Gib Screw	68-75	71A-75A	.10
AF	Binding Strap	68-75	71A-75A	.20
AG	Spring	68-75	71A-75A	.10
AH	Stop Lever Strap	68-75	71A-75A	.10
AI	Stock Rest	68-75	71A-75A	.30
AK	King Bolt	68-75	71A-75A	.15
AS	Length Gauge	68-75		.30
A4	Length Gauge, complete		71A-75A	2.00
AT	Right Hand Bottom Board	68-75	71A-75A	.75
AV	Left Hand Bottom Board	68-75	71A-75A	.75
BH	Stop Lever Strap Screw	68-75	71A-75A	.10
CH	Stop Lever Pin	68-75	71A-75A	.10
NA	Stop Lever Rod	71-75	71A-75A	.35
NB	Thumb Lever	71-75	71A-75A	.50
NC	Thumb Stop Lever	68-70		.50
ND	Saw Guide (Front)	68-73	71A-75A	.95
ND	Saw Guide (Rear)	68-73	71A-75A	.95
NH	Elevator	68-75	71A-75A	.50
NJ	Guide Stop Screw	68-75	71A-75A	.10
NK	King Bolt Stop Screw	68-75	71A-75A	.10
NL	Guide Stop	68-75	71A-75A	.10
NM	Stop Gauge (Front and Rear)	74-75	71A-75A	.15
NN	Stop Gauge Thumb Screw	68-75	71A-75A	.20
NO	Swinging Lever	68-70		4.00
NP	Stop Gauge (Front and Rear)	68-73	71A-75A	.15
NR	Sliding Front Post	74-75	71A-75A	1.30
NS	Sliding Front Post	71-73		1.25
NT	Swinging Lever	74-75	74A-75A	3.00
NU	Leg Screw	68-75	71A-75A	.10
NX	Swinging Lever	71-73	71A-73A	3.00
NY	Saw Guide (Front)	74-75	74A-75A	.95
NY	Saw Guide (Rear)	74-75	74A-75A	.95
OO	Indicator	68-75	71A-75A	.10
P	Stop Lever	68-75	71A-75A	.25
S5	Swinging Lever Bearing		71A-75A	.50
U	Leg	68-75	71A-75A	.50
W	Bed and Back	71-75	71A-75A	6.60
XO	Graduated Arc	68-75	71A-75A	.55
Z	Bed and Back	68-73		6.60

Parts NO, P, NR, NS, NT, U, W, NX and Z have corresponding letters cast in them, so, if in doubt, reference may be made to the castings.